




## QUICK CHANGER (ROBOT SIDE)



| REFERENCE    | INORMA     | A   | B     | C    | D      | G          | WEIGHT (g) |
|--------------|------------|-----|-------|------|--------|------------|------------|
| C10.AMRS-50  | NPC.QCR50  | 50  | 18.68 | -    | -      | M5(4x)     | 116        |
| C10.AMRS-90  | NPC.QCR90  | 90  | 18.30 | 53.6 | -      | G 1/8(8x)  | 345        |
| C10.AMRS-150 | NPC.QCR150 | 150 | 25.95 | 71.7 | 116.03 | G 1/4(10x) | 1158       |
| C10.AMRS-160 | -          | 160 | 25.95 | 71.7 | 116.03 | G 1/8(12x) | 1213       |
| C10.AMRS-200 | NPC.QCR200 | 200 | 30.60 | 87.5 | 175    | G1/4 (12x) | 2640       |

It is possible to provide 9 electrical connections.  
It works with pressured air or vacuum.