



MGS – Wall Mount for Quick Changer


Part No.	A	REF	Weight (g)
MGS-050	50	MGS-50	125
MGS-090	90	MGS-90	440
MGS-150	150	MGS-150/160	926
MGS-200	200	MGS-200	1178

Included mounting screws.

QC-P – Locating Pin


Part No.	L	H1	H2	H3	ØD1	ØD2	ØD3	ØD4	REF	Weight (g)
QC-P090065	65	2	5	5	18	8	20	14	MRS-90	190
QC-P150100	100	2,5	10	10	40	20	50	38,5	MRS-150	435
QC-P200120	120	3	11	15	50	25	60	43,5	MRS-200	950

To be positioned on the robot side.
It helps the manual centering of heavy EOATs.