

ARNOLD HIGH-PRESSURE MANUAL VICES FOR 5-AXES MACHING CENTER - SELF-CENTERING SC

ITEM: SELF-CENTERING SC

The ARNOLD SC vices are compact, tall, self-centring and highly precise vices that maintain their constant length, which makes them particularly suitable for work on machining centers with 5 controlled axes.



Tech. Code	Dim. mm	A mm	C mm	D mm	E mm	K mm	M H7 mm	N mm	U mm	V mm	X mm	Y mm	Weight mm
C6700090	90	250	100	130	93	115	20	30	71	11	100	5	6
C6700125	125	350	103	133	125	165			100		150		7

SET SUPPLIED WITH:

- base body
- mechanical worm without high pressure
- 1 set of jaws
- 1 set of plain jaws
- 1 ratchet key
- 1 crank
- 4 flanges
- instruction manual

ARNOLD BASE FOR ARNOLD SC VICES

ITEM: BASE SC

Base for 5 axes vice.

Tech. Code	C mm	B mm	A mm
C6725090	250	90	91
C6725125	350		126