



FITTINGS - G THREAD WITH O-RING

PX - Push In Male Threaded Y



Part No.	Ø A	G1		Weight (g)
PX04-G01	4	G1/8	10	
PX06-G01	6	G1/8	10	
PX06-G02	6	G1/4	10	

PB - Push In Male Threaded Branch T



Part No.	Ø A	G1		Weight (g)
PB04-M5	4	M5	10	8
PB04-G01	4	G1/8	10	13
PB06-M5	6	M5	10	12
PB06-G01	6	G1/8	10	14
PB06-G02	6	G1/4	10	22
PB08-G02	8	G1/4	10	25