


VACUUM FITTINGS FORM A



INORMA	D1	D2	G	L	L1	L2	L3	SW	CUP
NPC.AJJT07	3	2	M5	10.5	4.5	8	2	7	V
C10.A130.591	3.1	2.6	M5	13.2	4.5	8.4	2	8	M
C10.A140.005	3.2	2.2	M5	9.5	4	7	1	8	M
NPC.AJJT01	5	4	M5	14	4	7	3	7	V
C10.AF134	5.2	4	M5	17	4	8	6	8	M
C10.AJJT08	6	4	M5	12	4.5	8	2	7	M
C10.A140.405	6	4.9	M5	13	4	9	2	8	M
C10.A130.009	6.2	4.4	G1/8	17.5	8	13	2	14	M
C10.A130.301	6.3	6	M5	12	4.5	8	2	8	M
NPC.AJJT02	6.5	4.5	G1/8	21	8	13	2	14	V
C10.A130.013	6.5	6	M5	16	5	10	2.5	7	M
C10.A130.003	6.5	4	G1/8	20.2	7.7	13.7	3	14	M
NPC.AJJT03	6.7	4.5	M5	22.5	5.5	14.5	2	8	V
NPC.AJJT09	7	5.4	M5	13	5.4	7.4	2	8	V
C10.A130.030	10	6.7	G1/8	22	8	13	2	14	M
C10.A130.132	10.5	10	G1/8	31	9	17	7	13	M
C10.A130.190	12	8.7	G1/4	29	11	15	2	17	M
C10.A130.093	13	8.6	G1/8	23.3	9	11.3	2.3	13	M
C10.A130.281	14	9	G1/4	30.5	11	15	3.5	19	M
C10.A130.622	20	13.5	G1/4	40	11	17	4	22	M